

<b>MANAGER INFRASTRUCTURE AND AIRPORT'S REPORT</b> <b>September 2021</b>
---

The purpose of this report is to provide Councillors with an update on Infrastructure and Airport activity and works undertaken during the month of August:

Gravel Road Pothole Repairs	Coast Rd Memana Rd Palana Rd
Gravel Road Resheeting Works	Nil.
Maintenance Grading	Minor works undertaken in several locations.
Bitumen Road Reseal Works	Nil.
Bitumen Road Pothole Patching and Edging	Lackrana Rd Lady Barron Rd Whitemark streets
Waste Management	Transfer of waste from Killiecrankie and Lady Barron transfer stations to Whitemark. Scheduled attendance and coverage of waste and general clean up at Whitemark landfill. Whitemark landfill attendant roster continues to prove successful with residents. Site preparation works for the construction of the Whitemark transfer station was completed.
Drainage	The Bluff Track stormwater outlet was opened mid-June to allow the release of stormwater. The remaining pipework was laid but due to the rainfall, the water level in the pipe rose too high to allow the construction of the outlet headwall. The end pipe was undermined but this has been secured to stop further erosion. The headwall will be constructed once the water level has fallen.
Mowing and Gardening	Mowing was undertaken in Lady Barron and Whitemark residential streets, parks and foreshore, Emita Hall and sports ground. Regular maintenance of the Rose Garden.
Town Maintenance	Regular ongoing cleaning and maintenance of barbeques and seating.
Building Maintenance	Regular ongoing cleaning of public halls, toilets and gyms. The cleaning roster and responsibilities has been reorganised within the operation's staff, with further opportunities for improvements being implemented.
Vegetation Control	Steam weeding of various sections of footpaths and kerbing in Whitemark and Lady Barron proving to be very effective.
Quarries	Nil.
TasWater	Weekly and monthly water testing. Installation of three water meters undertaken.

Funerals	Nil
Airport	<p>NOTAM in place for aircraft arriving from mainland Australia.</p> <p>Airside Compliance areas, cones and gable markers being replaced / refurbished, 99% completed.</p> <p>Repainting old cones commenced.</p> <p>Ongoing mowing of runway strip and airport grounds.</p> <p>Sweeping of both runways and apron completed.</p> <p>Maintenance to grassed apron completed.</p> <p>Rectify bitumen pavement breakup on main apron.</p> <p>Cleaning of table drains and upgrade of stormwater drainage in and around airport buildings.</p> <p>Line-marking for dedicated hire car carparking completed.</p> <p>Public carpark area redesign works in progress.</p> <p>Removed old trees and debris adjacent to terminal building.</p> <p>Removed fire hazard trees behind private hangars and landscaped area.</p> <p>Staff continue studying for Certificate 3 in Airport Operations.</p> <p>COVID-19 airport response meeting on 12<sup>th</sup> August.</p> <p>Airport emergency exercise meeting on 17<sup>th</sup> August.</p> <p>Maintaining COVID-19 sanitizing of terminal, vehicles, workshop and office.</p> <p>RPT Passenger movements – 1298.</p>
Aircraft Landings	81 RPT, 25 Charter, 14 Private, 4 RFDS, 1 Helicopters.
Other	<p>Identification of Council plant and equipment continues.</p> <p>Preparation of capital works and maintenance programmes.</p> <p>Samples of gravel from Lughrata and Cann's Hill pits was sent to a soil laboratory for testing.</p> <p>First tranche of new roadworks signage ordered and delivered.</p>
Future Works planned for <i>September</i>	<p>Bluff track stormwater pipe installation and rehabilitation of track.</p> <p>Maintenance grading as weather allows.</p> <p>Bitumen pothole patching, and gravel road potholing as the weather allows.</p> <p>Commence gravel stockpiling at pits in preparation of resheeting programme beginning early October.</p>